## FIELD INSPECTION REPORT

Date of Inspection:		District: Parug	
Division: Danapuz		Length (km): 2 . 00	
Name of the Road:	NH 30 Goralya	Ashtuan to Mulani	pur Tola
Scheme/Programme:	MAINTENANCE	· ·	1 1 1 1
Package No.:		Road Id No.:	
Status of the Project:		I/Under Maintenance	
Work is a case of:		Jp gradation/ Maintenance	· almater de
Sl. No.	Parameters to	be checked	Remarks
Payement			
a) Road Junctio	n condition		SAL
b) Condition of	Surfacing		VS/II
c) Riding Quali	ty		√6/U_
d) Road Cambe	r		√\$/ <del>U</del> _
	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
	Contraction Joints provided or not (CC Pavement)		Yes/No-
g) Compaction	Compaction of tlank/slope & raincuts if any		Yes/No-
2. Cross Drain	nge	THE STATE OF	
a) Condition of	head walls in Hume pi	pe culverts including its painting	S/SRI/U
b) Condition of	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c) Condition of	Condition of railings/slab/approach for Bridges		S/SRI/U
3. Road Furnit	ure		
a) Whether sign stones/Pavem	n boards/informatory/ ent road markings are	cautionary Board/km & 200m provided and maintained	YesAle
4. Compliance	History		
a) Status of ATR	s & any others		

**Overall Rating** 

Satisfactory (S)	_
Satisfactory but requires Improvement (SRI)	2
Unsatisfactory (U)	

(BK SINGH) (SC SINGH) (SOMARU RANSIGNATURE)

NAME: JE JE

**DESIGNATION:**