

FIELD INSPECTION REPORT

Date of Inspection :		District : Bhagalpur	
Division : Bhagalpur.		Length (Km) : 1.174 km.	
Name of the Road : Radhanagar pataudi road to Besira paswan Tola			
Scheme / Programme : MMGSY (SC)			
Package No. :		Road Id No. : 20703213007	
Status of the Project : Ongoing / Completed / Under Maintenance			
Work is a case of : New Connectivity / Up gradation / Maintenance			
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S / U	
b)	Condition of Surfacing	S / U	
c)	Riding Quality	S / U	
d)	Road Camber	S / U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No	
f)	Contraction Joints provided or not (CC Pavement)	Yes / No	
g)	Cmpaction of flank/slope & raincuts if any	Yes / No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U	
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U	
c)	Condition of railings/slab/approach for Bridges	S / SRI / U	
3.	Road Furniture		
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No	
4.	Compliance History		
a)	Status of ATR's & any others		
Overall Rating			
Satisfactory (S)			
Satisfactory but requires Improvement (SRI)			
Unsatisfactory (U)			

Note :

BT cross damaged in some part of the road. surface is not good.

NAME :

DESIGNATION :

Ashmay
18.12.2020
J.C.

Signature
18/12/2020