

Date of Inspection:	5.12.20	District:	Vaishali
Division:	HA/MD	Length (km):	3.93 KM
Name of the Road:	Haripur to NH143		
Scheme/Programme:	MAINTENANCE		(New Minimum Policy)
Package No.:	HR-N/19-20/MD/MD	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	NA
b)	Condition of Surfacing	NA
c)	Riding Quality	NA
d)	Road Camber	NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	NA
g)	Compaction of flank/slope & raincuts if any	NA
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No only Informatory fix up
	Compliance History	
	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Signature
5/12.20
(Signature)

Brayesh Kumar

ATION: AE
Jandaha