

FIELD INSPECTION REPORT

Date of Inspection :	29/12/20	District :	East Champaran
Division :	DHAKA	Length (km):	0.90
Name of the Road:	Dhaka Pakari Dayal Road To Loham Dhaka		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	3-17 861 E+T)
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U NA	
b)	Condition of Surfacing	S/U NA	
c)	Riding Quality	S/U NA	
d)	Road Camber	S/U NA	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA	
g)	Compaction of flank/slope & raincuts if any	Yes/No NA	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No NA	
4.	Compliance History		
a)	Status of ATR's & any others	NA	

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

works not started

deia
(Signature) 29/12/20

NAME: Bindu Rajak

DESIGNATION: Executive Engineer

R-W-D.
Regional Laboratory Darbhanga