Date of Inspection: 28-12-20		District: WINT Champatan	
Division: R.w.D. wmo Div. Bether		Length (km): 2-415	
ame of the Road: 80			
cheme/Programme:	MAINTENANC		7/1
Berner Litte	5412-50 05	Road Id No.: 31808902	2011
Status of the Project:	Ongoing/Comple	eted/Under Maintenance ity/Up gradation/ Maintenance-~~~ W	unteranu
			Remarks
Sl. No.	Parameter	s to be checked	Vemarer
1. Pavement			9
a) Road Junction	Road Junction condition		
b) Condition of	Condition of Surfacing		
	Riding Quality		
112000000	Road Camber		
d) Road Cambe	Whether free from defects such as visible cracks, exposed		
e) whether it	aggregates in case of CC Pavement.		
	Contraction Joints provided or not (CC Pavement)		
	Compaction of flank/slope & raincuts if any		
2. Cross Drain	age		2
a) Condition of	Condition of head walls in Hume pipe culverts including its painting		
b) Condition of	Condition of Abutment & Wing walls, Slab in RCC culverts		
	Condition of railings/slab/approach for Bridges		
3. Road Furnit	ture		
a) Whether sig stones/Pavem	n boards/inform ment road marking	gs are provided and maintained	n Je
4. Compliance	History		
	l's & any others	- No	

Overall Rating

	C
Satisfactory (S)	3
Satisfactory but requires Improvement (SRI)	
(Insatisfactory (U)	

(Signature)

NAME: Rathesh Parmani DESIGNATION: Executive Engêneer