

Date of Inspection : 29.12.2020		District: W. Champaran.
Division : RMD. WORK. Div. Bafaka-I		Length (km): 0.740 km. (0.631 km)
Name of the Road: Gran Balua to Chanharua Main Road. Constructed.		
Scheme/Programme: MAINTENANCE		
Package No.: RM/WE/BKH/19/0001	Road Id No.: 31809007003	
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		Repair Maintenance.
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	-
f)	Contraction Joints provided or not (CC Pavement)	-
g)	Compaction of flank/slope & rainouts if any	yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	-
b)	Condition of Abutment & Wing walls. Slab in RCC culverts	S
c)	Condition of railings/slab approach for Bridges	-
3.	Road Furniture	
a)	Whether sign boards/informatory cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	yes
4.	Compliance History	
a)	Status of ATR's & any others	NU

CC Pavement is not provided

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Ratnesh Paswan,
DESIGNATION: Executive Engineer

29/12/2020
(Signature)