

FIELD INSPECTION REPORT

Date of Inspection : 29-12-2020		District: West Champaran
Division : R.W.D. - Muz Din-Bugahat		Length (km): 3.78 KM
Name of the Road: Dainmarwa to Phulwariya		
Scheme/Programme: MAINTENANCE		
Package No.: RM/RC/BAG/19/0008	Road Id No.: 31809102007	
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance <i>new maintenance</i>		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
f)	Contraction Joints provided or not (CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N.A
c)	Condition of railings/slab/approach for Bridges	
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	yes
4.	Compliance History	
a)	Status of ATR's & any others	NO

CC-pavement not provided

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

29/12/2020
(Signature)

NAME: Ratnesk Paswan
DESIGNATION: - Executive Engineer