

Date of Inspection : 29.12.2020		District: M. Champaran
Division : RWD. Work. Div. Bajbarah		Length (km): 6.70 km.
Name of the Road: PWD Road to Bakharaha.		
Scheme/Programme: MAINTENANCE		
Package No.: RM/WE/SAH/19-0010		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		Now. Maintenance.

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
f)	Contraction Joints provided or not (CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	Yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab approach for Bridges	
3.	Road Furniture	
a)	Whether sign boards/informatory cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes
4.	Compliance History	
a)	Status of ATR's & any others	No

C.C. Pavement is not provided

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

29/12/2020
(Signature)

NAME: - Ratnesh Paswan
DESIGNATION: Executive Engineer