

Date of Inspection : 29.12.2020		District: WEST. CHAMPARAN.
Division : RWD. WORK. DIV. BAHARA		Length (km): 3.88 km.
Name of the Road: PWD. Road to Semra.		
Scheme/Programme: MAINTENANCE		
Package No.: RM/WE/DAG/20-000		Lead Id No.: 31809102028
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		New Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
f)	Contraction Joints provided or not (CC Pavement)	
g)	Compaction of flank/slope & rainouts if any	
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab approach for Bridges	
3.	Road Furniture	
a)	Whether sign boards/informatory cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	
a)	Status of ATK's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

N.A.

This Road. is in tender process. work has not started

(Signature)

NAME:

Ratnesh Paswan.

DESIGNATION:

Executive Engineer