

Date of Inspection :	29.12.2020	District:	W. Champaran.
Division :	RWD. Work. Div. Bagaha-1	Length (km):	2.49 km.
Name of the Road:	PWD Road Dhokaha to Pipra.		
Scheme/Programme:	MAINTENANCE		
Package No.:	RM/WE/BAG/19-0010	Road Id No.:	31809102033
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance <i>new maintenance.</i>		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition —	S
b)	Condition of Surfacing —	S
c)	Riding Quality —	S
d)	Road Camber —	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
f)	Contraction Joints provided or not (CC Pavement)	—
g)	Compaction of flank/slope & raincuts if any	yes
2.	Cross Drainage	—
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab approach for Bridges	
3.	Road Furniture	
a)	Whether sign boards/informatory cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	yes
4.	Compliance History	
a)	Status of ATR's & any others —	NU

Sufficient
 S not provided

Overall Rating :

Satisfactory (S)	—	S
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

NAME: Ratnesk Paswan
 DESIGNATION: Executive Engineer

29/12/2020
 (Signature)