

FIELD INSPECTION REPORT

Date of Inspection : 29/12/2020		District: Nawada	
Division : Nawada		Length (km): 2.76 km.	
Name of the Road: Konyakol Bazar to Pachamba village			
Scheme/Programme: MAINTENANCE New			
Package No.: MR-N/19-20/HWD/09		Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		✓S
b)	Condition of Surfacing		✓S
c)	Riding Quality		✓SRU
d)	Road Camber		✓S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		NA/Yes/No
f)	Contraction Joints provided or not (CC Pavement)		NA/Yes/No
g)	Compaction of flank/slope & raincuts if any		✓Yes/No/raincuts.
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		✓S/SRU
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		NA/SRU
c)	Condition of railings/slab approach for Bridges		NA/SRU
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		✓Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRU)	
Unsatisfactory (U)	

29/12/2020
(Signature)

NAME: Sri Kant Prasad.
E.E.