

FIELD INSPECTION REPORT

Date of Inspection : 29/11/2020		District : NAWADA
Division : NAWADA		Length (km): 2.362 km
Name of the Road: P.W.D. Road to Gujjar Rock		
Scheme/Programme: MAINTENANCE NEW		
Package No.: MR-N/19-20 (MMR/17)		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S
b)	Condition of Surfacing	✓ S
c)	Riding Quality	✓ S
d)	Road Camber	✓ S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA/Yes/No
f)	Contraction Joints provided or not (CC Pavement)	NA/Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No/Remarks
2.	Cross Drainage	
a)	Condition of head walls in Flame pipe culverts including its painting	NA S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA S/SRI/U
c)	Condition of railings/slab approach for Bridges	NA S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Furniture not done. Work in progress.

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

S


29/11/2020
(Signature)

NAME:

Sri Kant Prasad.
E.E.