

FIELD INSPECTION REPORT

Date of Inspection : 29/12/2020		District: Nawada	
Division : Nawada		Length (km): 1.486 km.	
Name of the Road: Rd. Kousakol Road to Singhana			
Scheme/Programme: MAINTENANCE		New	
Package No.: MR-N/13-20/Nawada/17		Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		✓ S/U
b)	Condition of Surfacing		✓ S/U
c)	Riding Quality		✓ S/U
d)	Road Camber		✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		NA/Yes/No
f)	Contraction Joints provided or not (CC Pavement)		NA/Yes/No
g)	Compaction of flank/slope & raincuts if any		✓ Yes/No raincuts
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		✓ S/SRUU
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		NA S/SRUU
c)	Condition of railings/slab approach for Bridges		NA S/SRUU
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		No
Overall Rating : current painting & Furniture work in progress, Done			
Satisfactory (S)		S	
Satisfactory but requires Improvement (SRU)			
Unsatisfactory (U)			

NAME: Sri Kant Prasad
EE

MSB
29/12/2020
(Signature)