

FIELD INSPECTION REPORT

Date of Inspection:	29/12/2020	District:	Nawada
Division:	Rajauli	Length (km):	2.8 km
Name of the Road:	Roh. Siam Road to Karampur		
Scheme/Programme:	MAINTENANCE	Road Id No.:	3054
Package No.:			
Status of the Project:	Clapping/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓ S	
b)	Condition of Surfacing	✓ S	
c)	Riding Quality	✓ S	
d)	Road Camber	✓ S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	NA Yes/No	
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No raincuts	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA S/SRI/U	
c)	Condition of railings/slab approach for Bridges	NA S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	NO	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

S

NAME:

Sri Kant Arabel
E.E

29/12/2020
(Signature)