

FIELD INSPECTION REPORT

Date of Inspection :	19.12.2020	District:	Kaimur
Division :	Bhadrachal	Length (km):	1.59
Name of the Road:	Khanawa to Durganati Road.		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	10109637
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work Category:	New Connectivity/Up gradation/ Maintenance		

Sl.	Parameters to be checked	Remarks
1.	General	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Quality	S/U
d)	Grade	S/U
e)	Free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Drainage holes provided or not (CC Pavement)	Yes/No
g)	Condition of flack/slope & raincuts if any	Yes/No
2.	Structures	
a)	Condition of walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of Slab/Approach for Bridges	S/SRI/U
3.	Signage	
a)	Warning/informatory/cautionary Board/km & 200m markings are provided and maintained	Yes/No
4.	Other	
a)	Other	

0

Deficient (S)	
Deficient but requires Improvement (SRI)	
Deficient (U)	

New MR ongoing work, work under progress.

Mohamed
19.12.2020
(Signature)

NAME : Er. Arun Kumar Mahto.

DESIGN : S.E.