

### FIELD INSPECTION REPORT

|  |  |
|--|--|
| Date of Inspection : 20.12.2020                        | District: Kailash                          |
| Division : Bhabua                                      | Length (km): 2.5                           |
| Name of the Road: Saraiya gate to Mundazhori RCO Road. |  |
| Scheme/Programme:                                      | MAINTENANCE                                |
| Package No.:   | Road Id No.: 10301400817                   |
| Status of the Project:                                 | Ongoing/Completed/Under Maintenance        |
| Work is a case of:                                     | New Connectivity/Up gradation/ Maintenance |

| Sl. No.   | Parameters to be checked   | Remarks  |
|-----------|--|----------|
| <b>1.</b> | <b>Pavement</b>  |          |
| a)        | Road Junction condition  | ✓ S/U    |
| b)        | Condition of Surfacing   | ✓ S/U    |
| c)        | Riding Quality   | ✓ S/U    |
| d)        | Road Camber  | ✓ S/U    |
| e)        | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No   |
| f)        | Contraction Joints provided or not (CC Pavement)   | Yes/No   |
| g)        | Compaction of flank/slope & raincuts if any  | Yes/No   |
| <b>2.</b> | <b>Cross Drainage</b>  |          |
| a)        | Condition of head walls in Hume pipe culverts including its painting   | S/SRI/U  |
| b)        | Condition of Abutment & Wing walls, Slab in RCC culverts   | S/SRI/U  |
| c)        | Condition of railings/slab/approach for Bridges  | S/SRI/U  |
| <b>3.</b> | <b>Road Furniture</b>  |          |
| a)        | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No ✓ |
| <b>4.</b> | <b>Compliance History</b>  |          |
| a)        | Status of ATR's & any others   |          |

Overall Rating :

|   |   |
|---|---|
| Satisfactory (S)                            |   |
| Satisfactory but requires Improvement (SRI) | ✓ |
| Unsatisfactory (U)                          |   |

Sign Board Painting is ongoing.

  
 20.12.2020  
 (Signature)

NAME: Arun Kumar Mahato  
 EG