


FIELD INSPECTION REPORT

Date of Inspection :	01.12.2020	District :	MADRAS
Division :	ESHA RAG PUR - TARA PUR	Length (Km) :	2.76 Km
Name of the Road :	Lath Bazar Bigha Road to Vathur		
Scheme/Programme :	MAINTENANCE RML-4		
Package No. :	BA-202-136	Road Id No. :	
Status of the Project :	Ongoing/Completed/Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	S/A ✓	
b)	Condition of Surfacing	S/A ✓	
c)	Riding Quality	S/A ✓	
d)	Road Camber	S/A ✓	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No ✓	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓	
g)	Compaction of Bank/slope & raincut if any	Yes/No ✓	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U ✓	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U ✓	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary board/Km & 100m stones/Pavement road markings are provided and maintained	Yes/No ✓	
4	Compliance History		
a)	Status of ATRs & any others	Nil	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

NAME : LATH PRASAD
 DESIGNATION : AE


 (Signature)