FIELD INSPECTION REPORT

	And the second of the second o	
	of Inspection: 25-12-20 District: East cham	Janear
Divis	ion: Raxau Length (km): 1.74.46	Spare
NAME AND ADDRESS OF THE OWNER, WHEN	of the Road: Andhara Rup Bood to Doude	
	ne/Programme: MAINTENANCE MMGCX (12.12)	19
-	Road Id No. 217 a. a.	17000
Name and Address of the Owner, where the Persons of	- Song completed onder Maintenance	17002
Work	is a case of: New Connectivity/Up gradation/ Maintenance	to any transferred to the state of the state
SI. No	Parameters to be checked	Remark
1.	Pavement	
a)	Road Junction condition	SHU
b)	Condition of Surfacing	- S/U
c)	Riding Quality	\$/U
d) 	Road Camber	L81U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
l)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/8RI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	_S/SRI/U
c)	Condition of railings/slab/approach for Bridges	—S/SRI/U
3.	Road Furniture	
)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
.	Compliance History	

Overall Rating :

Satisfactory (S)	1
Satisfactory but requires Improvement (SRI)	3
Unsatisfactory (U)	

(Signature)

NAME: Sanjay/cum

DESIGNATION: Asst. Engineer.