

### FIELD INSPECTION REPORT

|                                               |  |                                             |  |
|-----------------------------------------------|--|---------------------------------------------|--|
| Date of Inspection : 23.12.2020               |  | District: Madhubani                         |  |
| Division : Madhubani                          |  | Length (km): 1.436 km.                      |  |
| Name of the Road: OLD NH to Sarisau Noniya To |  |                                             |  |
| Scheme Programme: MAINTENANCE                 |  |                                             |  |
| Package No.:                                  |  | Road Id No. ✓                               |  |
| Status of the Project:                        |  | Ongoing Completed Under Maintenance         |  |
| Work is a case of:                            |  | New Connectivity Up gradation Maintenance ✓ |  |

  

| Sl. No. | Parameters to be checked                                                                                             | Remarks     |
|---------|----------------------------------------------------------------------------------------------------------------------|-------------|
| 1.      | <b>Pavement</b>                                                                                                      |             |
| a)      | Road Junction condition                                                                                              | S/U U       |
| b)      | Condition of Surfacing                                                                                               | S/U U       |
| c)      | Riding Quality                                                                                                       | S/U U       |
| d)      | Road Camber                                                                                                          | S/U S       |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No Yes  |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No Yes  |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | Yes/No Yes  |
| 2.      | <b>Cross Drainage</b>                                                                                                |             |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U SRI |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U SRI |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U SRI |
| 3.      | <b>Road Furniture</b>                                                                                                |             |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No NO   |
| 4.      | <b>Compliance History</b>                                                                                            |             |
| a)      | Status of A I R's & any others                                                                                       | —           |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            | — |
| Satisfactory but requires Improvement (SRI) | — |
| Dissatisfactory (U)                         | 0 |

  
 23/12/20  


NAME:

M.A. Maholaz Bhau

DESIGNATION:

JE Pandey