

FIELD INSPECTION REPORT

Date of Inspection : 25.12.2020	District: Madhubani
Division : Madhubani	Length (km): 1.10
Name of the Road: PMUSY Road to Palwan for Prikasampur Baliq	
Scheme/Programme:	MAINTENANCE
Package No.: —	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance ✓
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U U
c)	Riding Quality	S/U U
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No/No
g)	Compaction of flank/slope & raincuts if any	Yes/No/No
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/US/1
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/US/1
c)	Condition of railings/slab/approach for Bridges	S/SRI/US/1
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No/No
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	U

[Signature]
25/12/2020
(Signature)

NAME: Mr. Manoj Kumar Jaiswal
DESIGNATION: JE Roadwork