

FIELD INSPECTION REPORT

Date of Inspection : 29-12-2020	District: Madhubani
Division : Madhubani	Length (km): 2.166 km
Name of the Road: Kuaatol To Kamalpur dhobi Tol To CPI Kuaatol	
Scheme/Programme: MAINTENANCE	
Package No.: —	Road Id No.: —
Status of the Project: Ongoing Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SU S
b)	Condition of Surfacing	SU S
c)	Riding Quality	SU S
d)	Road Camber	SU S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NO
f)	Contraction Joints provided or not (CC Pavement)	Yes/No Yes
g)	Compaction of flank/slope & raincuts if any	Yes/No Yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U SRI
c)	Condition of railings/slab/approach for Bridges	S/SRI/U SRI
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No /No
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

29-12-2020
(Signature)

NAME: Ashok Prasad Singh

DESIGNATION: AE, Pandaul