

FIELD INSPECTION REPORT

Date of Inspection : 28/12/2020	District: Patna
Division : Barh	Length (km): 1 Km
Name of the Road: Mamekhabad Gopkita Ponggy Road to Gopkita yodutala	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓U
b)	Condition of Surfacing	✓U
c)	Riding Quality	✓U
d)	Road Camber	✓U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/✓
f)	Contraction Joints provided or not (CC Pavement)	✓/No
g)	Compaction of flank/slope & raincuts if any	✓/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓SRI/U
c)	Condition of railings/slab/approach for Bridges	✓SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/✓ Board not Painted
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI) ✓

Unsatisfactory (U)

R.B. S. +
28/12/20
A.E.
(Signature)

NAME: Ram Bahadur B. S. +
A.E.