

FIELD INSPECTION REPORT		
DATE OF INSPECTION:	25/12/2020	DISTRICT: Purua
DIVISION:	Damda	LENGTH: 3.870 KM
NAME OF THE ROAD:	LOBO Bithali to Kamalpur Jager	
SCHEME/PROGRAMME:	PMOISY	MAINTENANCE
PACKAGE No:	ROAD ID No:	
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE	
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE	
SLNO	PARAMETERS TO BE CHECKED	REMARKS
1	PAVEMENT	
A	ROAD JUNCTION CONDITION	'S'
B	CONDITION FOR SURFACING	'S'
C	RIDING QUALITY	'S'
D	ROAD CAMBER	'S'
E	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE OF CC PAVEMENT	'S'
F	CONTRACTION JOINTS PROVIDED OR NOT (CC PAVEMENT)	'S'
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY	'S'
2	CROSS DRAINAGE	
A	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING	'S'
B	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	'S'
C	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	N.A
3	ROAD FURNITURE	
A	WHETHER SIGN BOARDS /INFORMATION BOARD/ KM & 200 M STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED	'S'
4	COMPLIANCE HISTORY	
A	STATUS OF ATR's & ANY OTHERS	N.A
OVERALL RATING		'S'
SATISFACTORY(S)		
SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)		
UNSATISFACTORY(U)		

25/12/2020
SIGNATURE

NAME: Surendra Prasad Singh
DESIGNATION: Junior Engineer