| | FIELD INSPECTION REPORT | |
|------------------------|---|------------|
| DATE OF INSPECTION: | | |
| אטונועוט: | 22/12/2020 MITRICTI PUZNER Dhamdaha IENUTII O.700KM | |
| NAME OF THE ROAD! | L048 to Bithaili Sarphal tola | |
| SCHTMT/PROGRAMME: | CYTSNY MAINTENANCE | |
| PACKAGE Not | I NOAD ID No.1 | |
| STATUS OF THE PROJECT: | ONGOING/COMPLETED/UNDER MAINTENANCE | |
| WORK IS A CASE OF: | NEW COMMECTIVITY/UP GIIADATION/MAINTENANCE | |
| 3L.NO | PARAMETERS TO BE CHECKED | REMARKS |
| 1 | PAVEMENT | |
| | | 'S' |
| A | ROAD JUNCTION CONDITION | 'S' |
| 0 | CONDITION FO SURFACING | 'S' |
| c | RIDING QUALITY | `s' |
| D | ROAD CAMBER | |
| t | WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE FO CC PAVEMENT | '2' |
| F | CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT) | 3' |
| Ġ | COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY | 3, |
| 2 | CROSS DRAINAGE | |
| | CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS | 'S' |
| A | PAINTING CHIVERTS | ٠ ئ |
| В | CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS | N.A |
| c | CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES ROAD FURNITURE | |
| 3 | | 'S' |
| Α | WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED | 7. |
| 4 | COMPLIANCE HISTORY | |
| | STATUS OF ATR'S & ANY OTHERS | N.A |
| | | |
| OVERALL RATING | SATISFACTORY(S) | 3" |
| | SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI) | |
| | UNSATISFACTORY(U) | 240 -6 |

NAME: Sirendra prosad Singh DESIGNATION: Junior Exgineer 50 - 20 1-2/12/12-20

SIGNATURE