

FIELD INSPECTION REPORT

Date of Inspection: .12.2020		District: Kishanganj	
Division: Kishanganj-1		Length(km): 1.0	
Name of the Road: PMGSY road to Senthala to Hatgaon.			
Scheme/Programme:		GTSNY.	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed /Under Maintenance ✓	
Work is a case of:		New Connectivity/ Up gradation / Maintenance ✓	
Sl. No	Parameters to be checked	Remarks	
1.	Pavement	✓S/U	
a)	Road Junction Condition	✓S/U	
b)	Condition of Surfacing	✓S/U	
c)	Riding Quality	✓S/U	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No	
f)	Contraction Joints Provided or not (CC Pavement)	✓Yes/No	
g)	Compaction of flank / shop & raincuts if any	✓Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its Painting	✓S/SRI/U	
b)	Condition of Abutment & Wing walls, slab in RCC culverts	✓S/SRI/U	
c)	Condition of railings/Slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	not ATR pending.	

Overall Rating :

Satisfactory(S)	"S"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

Sanj
30/12/2020
(Signature)

NAME: Sanjeev Kumar Paswan
J.E, RWD, Terhagachh