FIELD INSPECTION REPORT

Date	e of Inspection :	26.12.20	District: East cham	Jaran
Divi	Division: 2a × auf Length (km): 4.732			
-	ne of the Road: L	-034 - Lo27	Triveni to Bheriy	ahe'
The section of the case of	eme/Programme:	MAINTENANCE	Poss	Standard and a contract of the same description of a same
Withdraward Co. Strategics	age No.:	med () - Managamahanan galam menenggaran () - Tra dib derivatives / grama debis programa de (n.)	Road Id No.: 31708	50206
1 - Santa Company and address of the last	is of the Project:	Ongoing/Completed	Under Maintenance	
	k is a case of:	New Connectivity/U	p gradation/ Maintenance	
Sl. No.		Parameters to be checked		Remarks
1.	Pavement		manufacture of magazine, along and the individual of the field described at the participation of the matter described and the surrounding according to the control of the c	- 1
a) Road Junction of		condition	en franklinnskaladerid om some dimethod, at år minimistat fred til det platente y of å det allegensegt try at å	_S/O
b)	Condition of St	ırfacing		\87U
c)	Riding Quality			SPU
d)	Road Camber	423		LSHT
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No —
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No_
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			~S/8RI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
1)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
1.	Compliance Histo	ГŸ		
)	Status of ATR's &	any others		

Overall Rating

Satisfactory (S)	(5)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Shash blood Light DESIGNATION: J.E