FIELD INSPECTION REPORT

Date	of Inspection :	26.12.20	District: Fact char	Jacan
Division: Raxay			Length (km): 1. 40 km	
Name	All IN THE PARTY NAMED IN COLUMN TWO IS NOT THE	paramity. I delay combine paragraph to the delay delay and the second of the last of the l	to Gustanua	
Schen	ne/Programme:	MAINTENANCE	Pm6sy	THE BENEFIT (AS A ST.
-	ige No.:	The second state and the properties of 1 and the desiration (), the delta conference of the second state	Road Id No.: 31708	50206
	of the Project:	Ongoing/Complete	d/Under Maintenance	
Work	is a case of:	New Connectivity/	Up gradation/ Maintenance	eternia parte presenti intrograma delle esternizza delle
Sl. No.		Parameters to be checked		Remar
1.	Pavement			
a)	Road Junction condition			~570
b)	Condition of Surfacing			SHU
c)	Riding Quality			_S/U
d)	Road Camber			-810
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No,
g)	Compaction of flank/slope & raincuts if any			Yes/No-
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
:)	Condition of railings/slab/approach for Bridges			-S/SRI/U
3.	Road Furniture			
)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
	Compliance Histo	ıty		
5	Status of ATR's &	any others		

Overall Rating

Satisfactory (S)	(5)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Shathi Kant Singh

DESIGNATION: J. 13