-	-	FIELD INSPE	CTION REPORT	
Date of 1	inspection: 7	6.12.200	100000000000000000000000000000000000000	
Date of Inspection: 28.12.2020 Division: R.W.D. Durnagon Name of the Road: M.				2
Name of	the Road: Ne	Wanager A	ananti atradeta ba k	WARDT ET
Deal Deal	Programme:	MAINTENANCE	Length (km): 0,400 K	hendra De
			Road Id No.:	
			pleted/Under Maintenance	
Security of the same	a case of:	New Connectivity/t	Jp gradation/ Maintenance	
Sl. No.	i property	Parameters to	be checked	Remarks
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			√S/U
c)	Riding Quality			√S/U
d)	Road Camber			VS/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No.
0	Contraction Joints provided or not (CC Pavement)			N'es/No
g)	Compaction of flank/slope & raincuts if any			√Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U W
b)	Condition of Abutment & Wing walls. Slab in RCC culverts			S/SRITI N/
c)	Condition of railings/slab/approach for Bridges			S/SRIAU N/
3.	Road Furniture			
a) 1	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			1774
a)	Status of ATR's & any others			

Overall Rating

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

(Signature)

NAME:

DESIGNATION:

