

# FIELD INSPECTION REPORT

DATE OF INSPECTION:	22/12/2020	DISTRICT:	Purnea
DIVISION:	Bhondaha	LENGTH:	0.850 KM
NAME OF THE ROAD:	L028 Ramtola Sahaul to Sahaul		
SCHEME/PROGRAMME:	GTSNY	MAINTENANCE	
PACKAGE No:		ROAD No:	
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE		
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE		
SLNO	PARAMETERS TO BE CHECKED	REMARKS	
1	PAVEMENT		
A	ROAD JUNCTION CONDITION	'S'	
B	CONDITION OF SURFACING	'S'	
C	RIDING QUALITY	'S'	
D	ROAD CAMBER	'S'	
E	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE OF CC PAVEMENT	'S'	
F	CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)	'S'	
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY		
2	CROSS DRAINAGE		
A	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING	N.A	
B	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	N.A	
C	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	N.A	
3	ROAD FURNITURE		
A	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED	'S'	
4	COMPLIANCE HISTORY		
A	STATUS OF ATR's & ANY OTHERS	N.A	
OVERALL RATING			'S'
SATISFACTORY(S)			
SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)			
UNSATISFACTORY(U)			

NAME: Surendra Prasad Singh  
DESIGNATION: Junior Engineer

22/12/2020  
SIGNATURE