Date of	The state of the s	FIELD INSPE	CTION REPORT	
Divisio Name o	in: R.W.D. of the Road: N	6.12.2020	Length (km): 1.600 km	
Packag	e No.:	MAINTENANCE	Saashi soud to Car	gshank
Status	of the Project:		Road Id No.:	
Work is a case of:		Ongoing/Completed/Under Maintenance		
St. No.	The state of the s			
1.	Pavement	1 arameters to	be checked	Remarks
a)	Road Junction condition			
				√S/U
b)	Condition of Surfacing			✓ S/U
c)	Riding Quality			✓S/U
d)	Road Camber			VS/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U N
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U N
c)	Condition of railings/slab/approach for Bridges			S/SRI/U N
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			9-1
a)	Status of ATR's & any others			

Overall Rating

and the second s	
Satisfactory (S)	'3"
Satisfactory but requires Improvement (SRI)	11
Unsatisfactory (U)	

(Signature)

