

FIELD INSPECTION REPORT

Date of Inspection:	30-12-2020	District:	GAYA
Division:	Nirmal Bahadur	Length (Km.):	1.050
Scheme/Programme:	MAINTENANCE	Road Id No.:	
Package No.:	41871-2020-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68-69-70-71-72-73-74-75-76-77-78-79-80-81-82-83-84-85-86-87-88-89-90-91-92-93-94-95-96-97-98-99-100	Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/Maintenance	Remarks	
Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	S	L/S/U
b)	Condition of Surfacing	S	L/S/U
c)	Riding Quality	S	L/S/U
d)	Road Camber	S	L/S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes	L Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes	L Yes/No
g)	Compaction of flank/slope & rainouts if any	Yes	L Yes/No
2	Cross Drainage		L S/S/R/I/U
a)	Condition of head walls in Hume pipe culverts including its painting	NA	S/S/R/I/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA	S/S/R/I/U
c)	Condition of railings/slab/approach for Bridges		
3	Road Furniture		L Yes/No
a)	Whether sign boards/informatory/cautionary Board/lan & 200m stones/Pavement road markings are provided and maintained		
4	Compliance History	No ATR	
a)	Status of ATR's & any others.		S

Overall Rating

Satisfactory (S)	S
Satisfactory but requires improvement (SRI)	
Unsatisfactory (U)	

chhatrapati
30-12-2020
J.E