

FIELD INSPECTION REPORT


Date of Inspection: 30/12/2020		District: Kishanganj	
Division: Kishanganj-1		Length(km): 0.320 km	
Name of the Road: Naranga to L047			
Scheme/Programme: GTSNY			
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed /Under Maintenance ☒	
Work is a case of:		New Connectivity/ Up gradation / Maintenance ☒	

Sl. No	Parameters to be checked	Remarks
1.	Pavement	☒ S/U
a)	Road Junction Condition	☒ S/U
b)	Condition of Surfacing	☒ S/U
c)	Riding Quality	☒ S/U
d)	Road Camber	☒ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ☒
f)	Contraction Joints Provided or not (CC Pavement)	☒ Yes/No
g)	Compaction of flank / shop & raincuts if any	☒ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its Painting	☒ S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCG culverts	☒ S/SRI/U
c)	Condition of railings/Slab/approach for Bridges	☒ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ☒
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory(S)	-
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory(U)	.

NAME: RANJEET KUMAR


 (Signature) 30/12/20

AE