| | FIELD INSPECTION REPORT | |
|------------------------|---|-------------|
| DATE OF INSPECTION: | 22/12/2020 MITHIETI Purnea | |
| טועוטוסא: | Bhandaha IINOTIII 1.800 KM | |
| NAME OF THE ROAD: | Kataiya to Gahil Acthan | |
| SCHEME/PROGRAMMEL | MM. 61 S V MAINTENANCE | |
| PACKAGE No: | HOAD ID NO.L. | |
| STATUS OF THE PROJECTS | ONGOING/COMPLETED/UNDER MAINTENANCE | |
| WORK IS A CASE OF: | NEW CONNECTIVITY/UP ORADATION/MAINTENANCE | |
| 3LNO | PARAMETERS TO BE CHECKED | REMARKS " |
| 1 | PAVEMENT | |
| Α | | ,2, |
| | ROAD JUNCTION CONDITION | <i>'</i> 2' |
| <u> </u> | CONDITION FO SURFACING | '2' |
| | RIDING QUALITY | `S' |
| <u>D</u> | ROAD CAMBER | |
| t | WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE FO CC PAVEMENT | '2' |
| F | CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT) | 12. |
| G | COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY | `s' |
| 2 | CROSS DRAINAGE | |
| | CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS | `N.A' |
| A | CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS | ~.4' |
| В | | 'N. A' |
| c | CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES ROAD FURNITURE | |
| 3 | WHETHER SIGN DOARDS /INFORMATORY BOARD/ KM & 200 M | `s' |
| A | STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED | 3 |
| 4 | COMPLIANCE HISTORY | |
| <u> </u> | STATUS OF ATR'S & ANY OTHERS | N.4' |
| | | |
| OVERALL RATING | SATISFACTORY(S) | 131 |
| | SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI) | - |
| | LINSATISFACTORY(U) | |

NAME: Swendra prasad singh DESIGNATION: Junior Engineer