

FIELD INSPECTION REPORT		
DATE OF INSPECTION:	22/12/2020	DISTRICT: Purua
DIVISION:	Dhondaha	LENGTH: 1.00 KM
NAME OF THE ROAD:	Dibradham to Dibradham	
SCHEME/PROGRAMME:	MMGSY	MAINTENANCE
PACKAGE No:		ROAD ID No.:
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE	
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE	
SL NO	PARAMETERS TO BE CHECKED	REMARKS
1	PAVEMENT	
A	ROAD JUNCTION CONDITION	'S'
B	CONDITION TO SURFACING	'S'
C	RIDING QUALITY	'S'
D	ROAD CAMBER	'S'
E	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE OF CC PAVEMENT	'S'
F	CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)	'S'
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY	'S'
2	CROSS DRAINAGE	
A	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING	'S'
B	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	'S'
C	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	N.A
3	ROAD FURNITURE	
A	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED	'S'
4	COMPLIANCE HISTORY	
A	STATUS OF ATR's & ANY OTHERS	N.A
OVERALL RATING	SATISFACTORY(S) SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI) UNSATISFACTORY(U)	

NAME: Surendra Prasad Singh
 DESIGNATION: Junior Engineer

SABH
 22/12/2020
 SIGNATURE