Ramgash

FIELD INSPECTION REPORT

Date of Inspection: 27)11/2020	District: Kaimux	
Division: Moloniza,	Length (km):	
	asputtela Brahmantola.	
Scheme/Programme: MAINTENAN	NCE	
Package No.:	Road Id No.:	
Status of the Project: Ongoing/Com	Ongoing/Completed/Under Maintenance	
Work is a case of: New Connecti	New Connectivity/Up gradation/ Maintenance	

St. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	√S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	√S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
()	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	√Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	h. A.
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others 100	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Shriniwas Chardling