Date of Inspection: 2811770 D			District: Kaimur.	Audio de ciare destricto de debido de ser facilitar de la companya del companya de la companya de la companya del companya de la companya de	
Nivinian :			Length (km): 1.06		
Name of	Management of the second	chanethi do	Klanith' Rayforty	509.	
Scheme/	Programme:	MAINTENANCE		La propriese regular la regular con relación regular (la procesión el constitue el presenta de la presenta del La procesión de la procesión d	
Package No.:		eregistet blocker, component of the control of the	Rond Id No.:		
			ed/Under Maintenance // /Up gradation/ Maintenance	and the second s	
Work is a case of:		CONTRACTOR OF STATE O		Remarks	
Sl. No.	Parameters to be checked				
1.	Payement				
a)	Road Junction condition			✓S/U	
b)	Condition of Surfacing			/S/U	
c)	Riding Quality			✓S/U	
d)	Road Camber			✓ S/U	
e)	Whether fre	Yes/No			
n)	aggregates in case of CC Pavement. Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			√Yes/No	
2.	Cross Drainage				
a)	Condition of	S/SRI/U			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
e)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4.	Compliance History				
a)	Status of ATR's & any others			No.	
Overall	Pating .				
OVERALL	Datiniz *	100		- I	

Satisfactory (S)	5
Satisfactory but requires Improvement (\$RI)	
Unsatisfactory (U)	

(Signature)

NAME: Bhrisines Chow huf.