

FIELD INSPECTION REPORT		
DATE OF INSPECTION:	22/12/2020	DISTRICT: pursua
DIVISION:	Dhamdaha	LENGTH: 0.600 KM
NAME OF THE ROAD:	Biranchiya tala to Biranchiya school	
SCHEME/PROGRAMME:	MMGSY	MAINTENANCE
PACKAGE No:	ROAD ID No:	
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE	
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE	
SL NO	PARAMETERS TO BE CHECKED	REMARKS
1	PAVEMENT	
A	ROAD JUNCTION CONDITION	'S'
B	CONDITION FOR SURFACING	'S'
C	RIDING QUALITY	'S'
D	ROAD CAMBER	'S'
E	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE OF CC PAVEMENT	'S'
F	CONTRACTION JOINTS PROVIDED OR NOT (CC PAVEMENT)	'S'
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY	'S'
2	CROSS DRAINAGE	
A	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING	'N.A'
B	CONDITION OF ABUTMENT & WING WALLS. SLAB IN RCC CULVERTS	'S'
C	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	'N.A'
3	ROAD FURNITURE	
A	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED	'S'
4	COMPLIANCE HISTORY	
A	STATUS OF ATR's & ANY OTHERS	'N.A'
OVERALL RATING		
SATISFACTORY(S)		'S'
SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)		
UNSATISFACTORY(U)		

NAME: Surendra Prasad Singh
DESIGNATION: Junior Engineer

Sd/-
22/12/2020
SIGNATURE