

FIELD INSPECTION REPORT

Date of Inspection: 30/12/2020		District: HAWADA	
Division: NAWADA		Length (km): 5.00KM	
Name of the Road: NH-31 to Tetariya			
Scheme/Programme: MAINTENANCE		NEW	
Package No.: MR-N/19-20/HWD/11		Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			
S. No.	Parameters to be checked	Remarks	
1. Pavement			
a)	Road Junction condition	✓SU	
b)	Condition of Surfacing	✓SU	
c)	Riding Quality	✓SU	
d)	Road Camber	✓SU	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NAYes/No	
f)	Contraction Joints provided or not (CC Pavement)	NAYes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2. Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NAYes/No	
c)	Condition of railings/slab/approach for Bridges	NAYes/No	
3. Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4. Compliance History			
a)	Status of ATR's & any others	NO	

Overall Rating :

U.P. culvert painting and furni		
Satisfactory (S)	work in progress	S
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

NAME: Sri Kant Prasad.
E.E.

M/S
30/12/2020
(Signature)