

FIELD INSPECTION REPORT

Date of Inspection : 30/12/2020		District: Nawada	
Division : Nawada		Length (km): 2.500km.	
Name of the Road: Nawada Gaya Road to Shadiseri Belaghat			
Scheme/Programme:		MAINTENANCE New	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1. Pavement			
a)	Road Junction condition	✓ S/U	
b)	Condition of Surfacing	✓ S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	NA Yes/No	
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No remarks.	
2. Gross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	NA S/SRI/U	
3. Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No	
4. Compliance History			
a)	Status of ATR's & any others	NO	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

30/12/2020
(Signature)

NAME: Sri Kant Prasad.
E-E