

FIELD INSPECTION REPORT

Date of Inspection :	30/11/2020	District:	Nawada
Division :	Rajauli	Length (km):	3.05KM.
Name of the Road:	Sakara More to Garobigaha via Dhamalakhani Garobigaha Dalit tola		
Scheme/Programme:	MAINTENANCE	NEW	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
S.No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		✓SU
b)	Condition of Surfacing		✓SU
c)	Riding Quality		✓SU
d)	Road Camber		✓SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		NA/Yes/No
f)	Contraction Joints provided or not (CC Pavement)		NA/Yes/No
g)	Compaction of flank/slope & runcuts if any		✓Yes/No-runcuts.
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		✓S/SRU/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		NA/S/SRU/U
c)	Condition of railings/slab/approach for Bridges		NA/S/SRU/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		✓Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

30/11/2020
(Signature)

NAME: Sri Kant Prasad.
E.E.