

FIELD INSPECTION REPORT

Date of Inspection : 30/11/2020	District: Nawada	
Division : Rajauli	Length (km): 0.950km	
Name of the Road: Majhawa Tetariya to Katagharwa		
Scheme/Programme: MAINTENANCE NEW		
Package No.:	Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
1	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	✓SU
b)	Condition of Surfacing	✓SU
c)	Riding Quality	✓SU
d)	Road Camber	✓SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA/Yes/No
f)	Construction Joints provided or not (CC Pavement)	NA/Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA/S/SRI/U
c)	Condition of railings/slab/approach for Bridges	NA/S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

13/12
30/11/2020
(Signature)

NAME:

Sri Kant Prasad
E.E.