

FIELD INSPECTION REPORT

Date of Inspection :	24/11/2024	District :	Nawada
Division :		Length (km) :	1.465 km
Name of the Road :	Roh Sagar to Mahanagar.		
Scheme/Programme :	MAINTENANCE	NEW	
Package No. :		Road Id No. :	
Status of the Project :	Ongoing/Completed/Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/ Maintenance		
A. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Chamber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA Yes/No	
f)	Construction Joints provided or not (CC Pavement)	NA Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	NA S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA S/SRI/U	
c)	Condition of railings/slab approach for Bridges	NA S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	NA Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	NO	

Overall Rating :

No work progress.	
Satisfactory (S)	1
Satisfactory but requires Improvement (SRI)	2
Unsatisfactory (U)	U


 24/11/2024
 (Signature)

NAME: Sri Kant Prasad.

EE.