## FIELD INSPECTION REPORT

Date of Inspection: 1	8.12.2020	District: Kaimur	
Division: Mohania		Length (km): 10.20	1
Name of the Road: D'	hrato Patkhaul	iya Railway Corssing via Newros	Bajrkaun
Scheme/Programme:	MAINTENANCE		
Package No.:	and an internation of response values and the second resident property of the second s	Road Id No.: 10301500820	-
Status of the Project:	Ongoing/Completed/Under Maintenance		•
Work is a case of:	New Connectivity/L	Jp gradation/ Maintenance	

S1. No.	Pornmeters to be elecked	Remarks	
1.	Pavement	73.	
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	<b>YS/U</b>	
d)	Road Camber	<b>S</b> /U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
	Gross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
. <b>3</b>	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.4	Compliance History		
a)	Status of ATR's & any others		

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	V
Unsatisfactory (U)	

Sign board pointing I Bush culting required.

(Signature) 12-200

NAME: 12r. Arun Kumar Mahlo

DESIGNATION: S.E.