

FIELD INSPECTION REPORT

Date of Inspection: 28.12.2020		District: Samastipur
Division: RWD Dalsinghsarai		
Name of Road : 1075th Majraian Gola.		Length(km): 3.375 Km.
Scheme / Programme: MAINTENANCE		
Package No: NABARD.		
Status of the Project: Ongoing/Completed/Under Maintenance		Road Id No:
Work is a case of: New Connectivity/ Up gradation/ Maintenance		
Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	2
b)	Condition of Surfacing	2
c)	Riding Quality	2
d)	Road Camber	2
	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	2
e)	Construction Joint provided or not(CC Pavement)	2
f)	Compaction of flank/slope & raincuts if any	2
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	2
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	2
c)	Condition of railings/slab/approach for Bridge	2
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	2
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory(S)	5.
Satisfactory but requires Improvement(SRI)	
Unsatisfactory(U)	

NAME: Ben Choudhary Gupta
 DESIGNATION: Asst Engineer,
 MORDS,

(Signature)
 28/12/20