

FIELD INSPECTION REPORT

Date of Inspection: 24-12-20	District: Tamui
Division: Tamui	Length (km): 2.680
Name of the Road: L92-L90 Road TO Dahatand	
Scheme/Programme: MAINTENANCE / pm4sy	
Package No.:	Road Id No.: 20804100230
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SR/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	S.R.I
Unsatisfactory (U)	

Haison
24-12-20
JR

(Signature)

NAME:

DESIGNATION: