

FIELD INSPECTION REPORT

Date of Inspection: 26.12.2020	District: Samastipur	
Division: RWD Dalsinghsarai	Length(km): 2.435 km	
Name of Road : Dhamma chaur to Haribon kushwaha Tola		
Scheme / Programme:	MAINTENANCE	
Package No: MMBSY	Road Id No:	
Status of the Project: Ongoing/Completed/Under Maintenance ✓		
Work is a case of: ☒ New Connectivity/ ☐ Up gradation/ ☐ Maintenance		
Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	S
f)	Constraction Joint provided or not(CC Pavement)	S
g)	Compaction of flank/slope & raincuts if any	S
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	N.A
c)	Condition of railings/slab/approach for Bridge	N.A
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S
4	Compliance History	
a)	Status of ATR's & any others	N

Overall Rating :

Satisfactory(S)	S
Satisfactory but requires Improvement(SRI)	
Unsatisfactory(U)	

26.12.2020
(Signature)

NAME:

DESIGNATION :

Anil Prasad

OB