

FIELD INSPECTION REPORT

Date of Inspection: 21.12.2020		District: Samastipur	
Division: RWD Dalsinghsarai		Length(km): 8.45 km	
Name of Road: Akha Byslanpur path to mushar tola Hote Hue Paswan Tola.			
Scheme / Programme: MAINTENANCE			
Package No: MMGSY		Road Id No:	
Status of the Project: Ongoing/Completed/Under Maintenance ✓			
Work is a case of: ☒ New Connectivity/ Up gradation/ Maintenance			
Sl. No	Parameters to be Checked	Remarks	
1	Pavement		
a)	Road Junction Condition	S	
b)	Condition of Surfacing	S	
c)	Riding Quality	S	
d)	Road Camber	S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	S	
f)	Constraction Joint provided or not(CC Pavement)	S	
g)	Compaction of flank/slope & raincuts if any	SRI	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		
c)	Condition of railings/slab/approach for Bridge		
3	Road Furniture		
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	SRI	
4	Compliance History		
a)	Status of ATR's & any others	M	

Overall Rating :

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	SRI
Unsatisfactory(U)	


 21.12.2020
 (Signature)

NAME:

DESIGNATION :


