


# FIELD INSPECTION REPORT

Date of Inspection: 24.12.2020		District: Samastipur
Division: RWD Dalsinghsarai		Length(km): 0.690/km
Name of Road : Cross path Salampur Tasspur path to Dhobiola.		
Scheme / Programme: MAINTENANCE		
Package No: MM689	Road Id No:	
Status of the Project: Ongoing/Completed/Under Maintenance <input checked="" type="checkbox"/>		
Work is a case of: <input checked="" type="checkbox"/> New Connectivity/ <input type="checkbox"/> Up gradation/ <input type="checkbox"/> Maintenance		
Sl. No	Parameters to be Checked	Remarks
<b>1</b>	<b>Pavement</b>	
a)	Road Junction Condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	N.A
f)	Constraction Joint provided or not(CC Pavement)	N.A
g)	Compaction of flank/slope & raincuts if any	S
<b>2</b>	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N.A
c)	Condition of railings/slab/approach for Bridge	N.A
<b>3</b>	<b>Road Furniture</b>	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S
<b>4</b>	<b>Compliance History</b>	
a)	Status of ATR's & any others	ATR

Overall Rating :

Satisfactory(S)	S
Satisfactory but requires Improvement(SRI)	
Unsatisfactory(U)	

  
 24/12/2020  
 (Sign: are)

NAME:

DESIGNATION :

Anil Prasad

OB