(19)

FIELD INSPECTION REPORT

Date of Inspection: 26.12.2020		District: Samastipur	
Division: RWD Dalsinghsarai*		Length(km): 0770 km	
Nan	ne of Road: Chartwari Path to Moniga	Tola Moridih Harris	ian Tola.
_	eme / Programme: MAINTENANCE		
	kage No: MM Grs4	Road Id No:	
Stat	us of the Project: Ongoing/Completed/Under Main	ntenance	
Wor	k is a case of: New Connectivity/ Up gradat	tion/ Maintenance	_
SI. No	Parameters to be Check	ced	Rem: .ks
1	Pavement		
a)	Road Junction Condition		9
b)	Condition of Surfacing *		5
c)	Riding Quality		5
d)	Road Camber		9
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		5
f)	Construction Joint provided or not(CC Pavement)		9
g)			set
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		N'A
b)	Condition of Abutment & Wing walls, Slab in RC	CC culverts	Rest
c)	Condition of railings/slab/approach for Bridge		NID
3	Road Furniture		
a)	Whether sign boards/information/cautionary Board stones/Pavement road markings are provided and it	d/km & 200m naintained	S
4	Compliance History		
a)	Status of ATR's & any others		æ

Overall Rating :

Satisfactory(S)		
Satisfactory but requires Improvement(SRI)	SPE	
Unsatisfactory(U)		

(Signe are)

NAME: Amil Progent DESIGNATION: 05