

FIELD INSPECTION REPORT

Date of Inspection : 30.12.2020		District : Katihar
Division : Katihar		Length (Km) : 0.915
Name of the Road : Paswan Chowk to Mandal Telg		
Scheme/Programme :	Maintenance MMBSY (SC)	
Package No. :	Road ID No. :	
Status of the Project :	Ongoing/Completed/Under Maintenance ☒	
Work is a case of :	New Connectivity/Up gradation/Maintenance ☒	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ☒
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA ☒
g)	Compaction of Flank/Slope & Raincuts if any	Yes/No ☒
a)	Condition of Head walls in Hume Pipe Culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U NA ☒
c)	Condition of Railings/Slab/Approach for Bridges	S/SRI/U
a)	Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained	Yes/No ☒
a)	Status of ATR's & any others	ND

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SR I
Unsatisfactory (U)	


 Executive Engineer
 RWD, Works Division, Katihar